



[4910-13-P]

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2012-0631; Directorate Identifier 2011-SW-021-AD;

Amendment 39-17282; AD 2012-25-01]

RIN 2120-AA64

Airworthiness Directives; Eurocopter France Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for Eurocopter France Model AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350C, AS350D, AS350D1, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP helicopters with certain Aerazur emergency flotation gear attachment brackets (brackets) installed. This AD requires an initial and recurring inspection of the brackets for a crack, and if there is a crack, replacing the cracked bracket with an airworthy bracket. This AD was prompted by reports of cracks on the brackets. The actions of this AD are intended to prevent failure of the emergency flotation system and loss of float stability in the event of a water landing.

DATES: This AD is effective [INSERT DATE 35 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

The Director of the Federal Register approved the incorporation by reference of certain documents listed in this AD as of [INSERT DATE 35 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

ADDRESSES: For service information identified in this AD, contact American Eurocopter Corporation, 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.eurocopter.com/techpub>. You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the Docket Operations Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, any incorporated-by-reference service information, the economic evaluation, any comments received, and other information. The street address for the Docket Operations Office (phone: 800-647-5527) is U.S. Department of Transportation, Docket Operations Office, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Robert Grant, Aviation Safety Engineer, Safety Management Group, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5110; email robert.grant@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

On June 18, 2012, at 77 FR 36216, the Federal Register published our notice of proposed rulemaking (NPRM), which proposed to amend 14 CFR part 39 to include an AD that would apply to Eurocopter France Model AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350C, AS350D, AS350D1, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP helicopters with a bracket, part number (P/N) 158172, 158173, 158288, or 158289, installed. That NPRM proposed to require an initial and recurring inspection of the brackets for a crack, and if there was a crack, replacing the cracked bracket with an airworthy bracket. The proposed requirements were intended to prevent failure of the emergency flotation system and loss of float stability in the event of a water landing.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, issued EASA AD No. 2011-0072, dated April 20, 2011 (AD 2011-0072), to correct an unsafe condition for the Eurocopter AS350B, AS350BA, AS350BB, AS350B1, AS350B2, AS350B3, AS350D, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP helicopters with Aerazur emergency flotation gear attachments installed. EASA stated it received several reports of cracks being found on the brackets which appear to be caused by stress corrosion. This condition, if not corrected, could result in “rupture of the emergency flotation gear attachment brackets” during a water landing. The helicopter’s float stability could no longer be ensured, possibly resulting in damage to the helicopter and injury to the

occupants. EASA's AD requires an initial inspection of the brackets, replacement of any brackets found with cracks, and re-inspection of the brackets every 13 months.

Comments

We gave the public the opportunity to participate in developing this AD, but we received no comments on the NPRM (77 FR 36216, June 18, 2012).

FAA's Determination

These helicopters have been approved by the aviation authority of France and are approved for operation in the United States. Pursuant to our bilateral agreement with France, EASA, its technical representative, has notified us of the unsafe condition described in the EASA AD. We are issuing this AD because we evaluated all information provided by EASA and determined the unsafe condition exists and is likely to exist or develop on other helicopters of these same type designs and that air safety and the public interest require adopting the AD requirements as proposed except we are incorporating a figure by reference instead of including it in our AD to meet current publication requirements. This change is consistent with the intent of the proposals in the NPRM (77 FR 36216, June 18, 2012) and will not increase the economic burden on any operator nor increase the scope of the AD.

Interim Action

We consider this AD interim action. Eurocopter is developing a modification that will address the unsafe condition identified in this AD. Once this modification is developed, approved, and available, we might consider additional rulemaking.

Differences Between this AD and the EASA AD

Differences between this AD and the EASA AD include:

- The EASA AD applies to Eurocopter Model AS 350 BB helicopters. This AD does not as this model is not type certificated by the FAA. Additionally, the EASA AD excludes Eurocopter Models AS350C and AS350D1, whereas this AD includes them.
- The EASA AD mandates different compliance times depending on the manufacture date of the helicopter. We mandate inspecting all helicopters within 110 hours TIS or 3 months, whichever occurs first, regardless of date of manufacture.
- This AD does not require returning cracked brackets to the manufacturer.

Related Service Information

Eurocopter issued Alert Service Bulletin (ASB) No. AS350-05.00.63, Revision 1, dated April 18, 2011, and ASB No. AS355-05.00.58, Revision 1, dated April 18, 2011. These ASBs specify procedures to inspect the front and rear brackets at regular intervals. EASA classified these ASBs as mandatory and issued EASA AD 2011-0072 to ensure the continued airworthiness of these helicopters.

Costs of Compliance

We estimate that this AD will affect 733 helicopters of U.S. Registry and that labor rates will average \$85 an hour. Inspecting the brackets will take about 4 work-hours per inspection cycle for a labor cost of \$340 per helicopter and \$249,220 for the U.S. fleet. Replacing the bracket, if needed, will require about 1 work-hour and about \$1,130 for the parts. Thus, the total cost to replace one bracket will be about \$1,215.

Authority for this Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on helicopters identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
- (3) Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction; and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared an economic evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39 - AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2012-25-01 **EUROCOPTER FRANCE:** Amendment 39-17282;

Docket No. FAA-2012-0631; Directorate Identifier 2011-SW-021-AD.

(a) Applicability.

This AD applies to Eurocopter France Model AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350C, AS350D, AS350D1, AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP helicopters with an Aerazur emergency flotation gear attachment bracket, part number 158172, 158173, 158288, or 158289, installed, certificated in any category.

(b) Unsafe Condition.

This AD defines the unsafe condition as a crack in an attachment bracket of the emergency flotation gear. This condition could result in failure of the emergency flotation system and loss of float stability in the event of a water landing.

(c) Effective Date.

This AD becomes effective [INSERT DATE 35 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

(d) Compliance.

You are responsible for performing each action required by this AD within the specified compliance time unless accomplished previously.

(e) Required Actions.

Within 110 hours time-in-service or 3 months, whichever occurs first, and thereafter at intervals not to exceed 13 months:

(1) Using a 5X or higher power magnifying glass, visually inspect the front emergency flotation gear attachment bracket, section B-B, item (e) in Areas F, G, and H of Figure 1 of Eurocopter Alert Service Bulletin No. AS350-05.00.63 or No. AS355-05.00.58, both Revision 1, and both dated April 18, 2011, as applicable to your model helicopter (ASB); and the rear emergency flotation gear attachment bracket, section A-A, item (a) in Areas D and E of Figure 1 of the ASB, for a crack.

(2) If there is a crack, replace the cracked emergency flotation gear attachment bracket with an airworthy emergency flotation gear attachment bracket prior to reinstallation of the emergency flotation equipment.

(f) Alternative Methods of Compliance (AMOCs).

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Robert Grant, Aviation Safety Engineer, Safety Management Group, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5110; email robert.grant@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

(g) Additional Information.

The subject of this AD is addressed in European Aviation Safety Agency AD No. 2011-0072, dated April 20, 2011.

(h) Subject.

Joint Aircraft Service Component (JASC) Code: 2560, Emergency Equipment.

(i) Material Incorporated by Reference.

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Eurocopter Alert Service Bulletin (ASB) No. AS350-05.00.63, Revision 1, dated April 18, 2011.

(ii) Eurocopter ASB No. AS355-05.00.58, Revision 1, dated April 18, 2011.

(3) For Eurocopter service information identified in this AD, contact American Eurocopter Corporation, 2701 N. Forum Drive, Grand Prairie, Texas 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.eurocopter.com/techpub>.

(4) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to:

<http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Fort Worth, Texas, on April 12, 2013.

Lance T. Gant,

Acting Directorate Manager, Rotorcraft Directorate,
Aircraft Certification Service.

[FR Doc. 2013-09437 Filed 04/30/2013 at 8:45 am; Publication Date: 05/01/2013]